






1	One set of screw plungers
2	Power cord
3	Left and right housing
4	PCB speed control board
5	Cable sheath
6	Speed control key/cover
7	Pressing board
8	Switch
9	Switch Sheath
10	Switch osculant staff
11	Motor
12	Spline sleeve
13	Rubber ring
14	Spline
15	Plastic head housing
16	Seal ring
17	Bearing
18	Output axis
19	S/S tube
20	Oil seal
21	Bearing sleeve
22	Knife protector
23	Ceramic ring sleeve
24	Ceramic ring
25	Graphite ring spring
26	Graphite ring
27	Convex ring
28	Blade