




Ref.	Spare part	Quant.			
1	left side board	1	39	locating shaft support	1
2	right side board	1	40	mian shaft connector 1	1
3	mian shaft	1	41	mian shaft connector 2	1
4	1 motor base 1	1	42	blank	1
5	2 motor base 1	1	43	rest sleeve	4
6	square shaft	2	44	fixed block	1
7	thickness adjusting plate (right)	1	45	Rubber foot	4
8	thickness adjusting plate (left)	1	46	The "A" type belt L=686	1
9	shaft 1 $\Phi 12 \times 462$	1	47	handle M8*25	3
10	shaft 2 $\Phi 10 \times 460$	1	48	Cable fixing head	1
11	shaft 3 $\Phi 19 \times 462$	1	49	motor	1
12	Handle fastener	4	50	Switch	1
13	inlet board	1	51	M14 screw nut M14	1
14	Front side board	1	52	bearing 6201	4
15	Upper cover	1	53	bearing 6202	2
16	Outlet fixing plate	1	54	bearing 6203	2
17	bearing block	2	55	bearing 6204	2
18	inlet board	1	56	saw blade	32
19	left support rod	1	57	Saw blade tensioning piece	64
20	right support rod	1	58	spring	32
21	big belt fixed shaft	1	59	Saw blade holder 12mm	2
22	nameplate	1			
23	saw blade support component	1			
24	saw blade support component	1			
25	raising baffle component	1			
26	Transmission shaft spacer	1			
27	nut M6	4			
28	Ring	1			
29	knife rest support	2			
30	big belt wheel	1			
31	support block	1			
32	small belt wheel	1			
33	short transmission shaft 1	1			
34	short transmission shaft 2	1			
35	knife rest sliding rod	2			
36	spacer	4			
37	belt wheel connect rod	1			
38	locating shaft	2			